


Wilson.

Stringing Instructions



Burn 100LS

String Pattern

18 Mains x 16 Crosses

String Length

One 37' (11.0 m) length (ss: 10') or 20' (6.1 m) mains and 17' (5.2 m) crosses. Start mains at head.

Mains skip 8H, 10H and 9T. Tie off mains at 6T.

Shared holes 7T and 8T.

If one-piece stringing: Start X's at 8T. Tie off X's at 6H.

If two-piece stringing: Start X's at 8H. Tie off X's at 5T,6H.

Recommended String Tension

50 - 60 lbs. (23 - 27 kgs.)